UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION VII 374 FAST ELEVENTH STREET SANSAS CITY MISSOURI - 8416.5

JUN 01 1983

Mr. Tom Robertson
PEDCo Project Manager
PEDCo Environmental, Inc.
2420 Pershing Road
Crown Center, Suite 300
Kansas City, Missouri 64108

RECEIVED

Mike Janderson

JUN 0 2 1983

AIR AIND MALARDOUS MATERIALS
DIVISION

Dear Mr. Robertson:

Enclosed are specific task assignments and related documents for the following facilities:

Emerson Electric MOD006269633
Alcolac, Inc. MOD084093368
McDonnell Douglas MOD000818963
Litton Clifton IAD005268420
Thompson-Hayward IAD005277231

These specific task assignments are requested under Contract No. 68-01-6515, Work Assignment No. RO7-004 (Change No. 2), Subtask 4, PN 3597-17-4.

The specific task assignments indicate the actual tasks to be performed, materials transmitted to you, the target dates for completion of the task, and the contact person at EPA Region VII for each task.

Please return all reference materials upon completion of a specific task assignment.

If you have any questions, please contact Joe Galbraith at (816) 374-6531.

Sincerely yours,

Dennis A. Degner, Ph.D., P.E.

Sr. Environmental Engineer

Permits Section

Waste Management Branch

Air and Waste Management Division

Enclosures

cc: John Bruck, P.E., PEDCo Project Director Charles Saunders, A.T. Kearney, Regional Liaison James Levin, A. T. Kearney, Program Manager

R00144177

RCRA RECORDS CENTER

Facility: Emerson Electric (St. Louis)

EPA No.: MOD006269633

Specific Task:

1. Conduct RCRA compliance inspection.

Please note that facility claims confidentiality based on national security.

Materials Transmitted to Contractor:

- 1. RCRA inspection checklist.
- Part B application (less one drawing for which confidentiality is claimed.)

Specific Reports:

1. Verify compliance with interim status regulations.

Target Date for Completion of Task: August 1, 1983

Contact Person: Joe Galbraith - (816) 374-6531

Facility: Alcolac, Inc. (Sedalia)

EPA No.: MOD084093368

Specific Task:

- 1. Conduct RCRA compliance inspection.
- 2. Provide site description and/or photographs of tanks and tank storage area, and container storage area.

Please note that facility has made a claim of confidentiality for process information.

Materials Transmitted to Contractor:

- 1. RCRA inspection checklist.
- 2. Part B application (to be transmitted to contractor as confidential material under separate cover).

Specific Reports:

- 1. Verify compliance with RCRA interim status regulations.
- 2. Site description and/or photographs as indicated above.

Target Date for Completion of Task: August 1, 1983

Contact Ferson: Luetta Flournoy - (816) 374-6531

Facility: McDonnell Douglas (Hazelwood)

EPA No.: MOD000818963

Specific Task:

- 1. Conduct RCRA compliance inspection.
- 2. Check status of overflow pipes on poly tanks to verify compliance with design requirements in 40 CFR Part 264.
- 3. Check on presence and adequacy of warning signs.
- 4. Verify continuity and adequacy of containment for container storage area.

Materials Transmitted to Contractor:

- 1. RCRA inspection checklist
- 2. Part B application less confidential information

Specific Reports:

- 1. Verify compliance with RCRA interim status regulations.
- 2. Information requested in items 2, 3 and 4 of above specific tasks.

Target Date for Completion of Task: August 1, 1983

Contact Person: Stephen Busch - (816) 374-6531

Facility: Litton-Clifton Precision Instruments (Davenport)

EPA No.: IAD005268420

Specific Task:

- 1. Conduct RCRA compliance inspection.
- Check current container storage area for any problems that could prevent or delay closure. This area will be closed when new storage area is constructed.

Materials Transmitted to Contractor:

- 1. RCRA inspection checklist.
- 2. Part B application.

Specific Reports:

- 11. Verify compliance with RCRA interim status regulations.
- 2. Report any potential problems for closure of current container storage area.

Target Date for Completion of Task: August 1, 1983

Contact Person: Joe Galbraith - (816) 374-6531

Facility: Thompson Hayward (Pleasant Hill)

EPA No.: IAD005277231

Specific Task:

- 1. Conduct RCRA compliance inspection.
- Verify quantity of drums, aisle space, any containment design features, provisions to prevent run-on, provisions to prevent reactions, etc., as these pertain to Dixie Building.
- 3. Check status of previous container storage area regarding proper closure.
- 4. Check status of temporary waste pile of contaminated material due to spill earlier.

Materials Transmitted to Contractor:

- 1. RCRA inspection checklist.
- 2. Part B application.
- 3. Deficiency letters for Part B submissions.

Special Notes:

1. Facility has received deficiency letters regarding Part B material. Compliance order is pending as a result of late submittals. Dramatic increase in capacity during interim status without specific authorization. Compliance action is a possibility for this and deficiencies noted during inspection.

Target Date for Completion of Task: August 15, 1983

Contact Person: Joe Galbraith - (816) 374-6531